Approved For Release 2002/10/16: CIA-RDP72B00464R000400060056-5

21 September 1970

/2 cys. encl.

. encl.

25X1

Subject:

Contract (657)-12846 Follow-On EMR

Monthly Technical Progress Report Period Ending 31 July 1970

Dear Burt:

JM:vg Encl.

cc:

SPO

ASPO

In fulfillment of the subject obligation enclosed please find one (1) copy of this Contractor's report No. 78.

Regards, Jim

STATINTL

FOR OFFICIAL USE ONLY Approved For Releaser 200200116 FEARBAN 200464R000400060056-5

2641-70

STATINTL

CONTRACTOR

MONTHLY LETTER REPORT
1940-L-78

STATINTL

(F/0 EMR)
CONTRACT: (657)-12846 25X1

REPORT PERIOD: AUGUST 1970

APPROVED BY

FOR OFFICIAL USE ONLY Approved For Release 12002/12/06/2014 RDB72800464R000400060056-5

Only outstanding Contract Items are listed hereunder. NOTE: BASIC CONTRACTUAL OBLIGATIONS W/S Item V - Configuration Records Contractor's correspondence to SPO of 21 July 1970 submitted recommendations for disposition of records. Contracting Officer's letter of 4 August 1970 approved recommendations - Records will be STATINTL retained by Contractor until such time as they will provide no significant program benefit, at which time they will be destroyed. ITEM CONSIDERED CLOSED & WILL BE DELETED FROM SUBSEQUENT REPORT OPTIONAL REQUIREMENTS (Spare Parts) Nomenclature Qty. Remarks Pt. No. List No. Seq. No. 024600 542065-1 Sense Card 1 EDD 11/70 (*) 4 Ass'y STATINTL (*) Under prior report | forwarded | | correspondence of TATINTL 25 June 1970 relating to problems being encountered in transistor selection and/or availability. STATINTL is pursuing two parallel courses. Adding capacitors to present modules to slow down transistor switching time. Purchasing new transistors and selecting them to 2. work in modules. is endeavoring to accomplish item I above as this means STATINTL that the present modules could be reworked and the 11/70 date most likely met. STATINTL shows that there Preliminary engineering investigation by is enough room around outside of existing module to add capacitor. | module assembly vendor is presently STATINTL evaluating feasibility of repairing present module. STATINTL If item 2 is the only feasible solution would have to completely rebuild the 13 Sense Amplifier modules used in

the Sense Card Ass'y. as the present transistors cannot

be removed and replaced (potted cordwood module). This would involve a whole new procurement cycle and EDD would be 6 - 8

Page 1 of 1

UNCLASSIFIED Approved For Release 2002/10/16 : CIA-RDP72B00464R000400060056-5

OSA -2640 - 70

7327 21 September 1970

Subject:

Contract AF33(657)-12846 Follow-On EMR Program

Monthly Fiscal Report, Submittal of

Dear Burt:

Enclosed please find this Contractor's "Monthly Fiscal Report #77" for the period ending 30 August 1970.

Regards,

Jim

JM:vg Encl.

cc:

SPO

STATINTL

Jacker ay

FOR OFFICIAL USE ONLY Approved For Release 2002/10 16 WCIAPROP BE001464R000400060056-5 OSA -2640-70 STATINTL CONTRACTOR FINANCIAL STATUS REPORT (F/O EMR) 657)-1284625X1 CONTRACT: August 1970 REPORT PERIOD:

STATINTL

APPROVED